

Division of Health Service Regulation

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION	(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER: HAL086002	(X2) MULTIPLE CONSTRUCTION A. BUILDING: 01 B. WING: _____	(X3) DATE SURVEY COMPLETED R 09/24/2015
--	---	---	---

NAME OF PROVIDER OR SUPPLIER
COLONIAL LONG TERM CARE FACILITY

STREET ADDRESS, CITY, STATE, ZIP CODE
340 SNOWHILL DRIVE
MOUNT AIRY, NC 27030

(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETE DATE
(C 000)	Initial Comments This report is of a Followup Survey done by Bob Getchell on September 24, 2015. The Followup survey revealed that all deficiencies have not been corrected, therefore a new plan of correction is required.	(C 000)		
(C 132)	Bathrooms-Must Provide Privacy SECTION .0300 - PHYSICAL PLANT 10A NCAC 13F .0305 PHYSICAL ENVIRONMENT (e) The requirements for bathrooms and toilet rooms are: (5) The bathrooms and toilet rooms shall be designed to provide privacy. Bathrooms and toilet rooms with two or more water closets (commodes) shall have privacy partitions or curtains for each water closet. Each tub or shower shall have privacy partitions or curtains; This Rule is not met as evidenced by: 1. Based on observation, the facility failed to ensure that plumbing fixtures, like toilets, tubs and showers, are designed to provide privacy in group settings. Followup Findings on September 24, 2015: a. There are no privacy curtains or partitions provided in the Group Bathrooms throughout the facility.	(C 132)	CONSTRUCTION OCT 19 2015 Partitions have been installed and curtains hung.	10-19-15
(C 164)	Housekeeping and Furnishings-Clean, Repaired SECTION .0300 - PHYSICAL PLANT 10A NCAC 13F .0306 HOUSEKEEPING AND FURNISHINGS (a) Adult care homes shall: (1) have walls, ceilings, and floors or floor	(C 164)		

Division of Health Service Regulation
LABORATORY DIRECTOR'S OR PROVIDER/SUPPLIER REPRESENTATIVE'S SIGNATURE

Mark Payne

Admin

10-16-15

STATE FORM

WH0X22

If continuation sheet 1 of 8

Division of Health Service Regulation

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION	(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER: HAL086002	(X2) MULTIPLE CONSTRUCTION A. BUILDING: 01 B. WING: _____	(X3) DATE SURVEY COMPLETED R 08/24/2015
--	---	---	---

NAME OF PROVIDER OR SUPPLIER STREET ADDRESS, CITY, STATE, ZIP CODE

COLONIAL LONG TERM CARE FACILITY 340 SNOWHILL DRIVE
MOUNT AIRY, NC 27030

(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETE DATE
(C 164)	Continued From page 1 coverings kept clean and in good repair; (2) have no chronic unpleasant odors; (3) have furniture clean and in good repair; (e) This Rule shall apply to new and existing facilities. This Rule is not met as evidenced by: 2. Based on Observation, the facility failed to have walls, ceilings, and floors or floor coverings, kept clean and in good repair. Followup Findings on September 24, 2015: a. Bedroom 9 walls need cleaning. 3. Based on Observation, the facility failed to provide an environment in accordance with this Rule. This would affect all residents, staff and visitors by exposing them to, unclean conditions and equipment in disrepair. Followup Findings on September 24, 2015: a. The connection of the commode to the floor was loose in Bathroom near Bedroom 22.	(C 164) C164A C164 3A	Bedroom walls in Rm 9 Have been cleaned Housekeeping clean the walls on weekly basis Commode near Rm 22 HAS been tightened down Maintenance will check all commodes monthly -	10-19-15 10-19-15
(C 166)	Housekeeping-Maintained Free of Hazards SECTION .0300 - PHYSICAL PLANT 10A NCAC 13F .0306 HOUSEKEEPING AND FURNISHINGS (a) Adult care homes shall: (5) be maintained in an uncluttered, clean and orderly manner, free of all obstructions and hazards; (e) This Rule shall apply to new and existing facilities. This Rule is not met as evidenced by: 1. Based on Observation, the facility failed to provide an environment in accordance with this	(C 166)		

Division of Health Service Regulation

STATE FORM

8899

WH0X22

If continuation sheet 2 of 6

Division of Health Service Regulation

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION	(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER: HAL086002	(X2) MULTIPLE CONSTRUCTION A. BUILDING: 01 B. WING: _____	(X3) DATE SURVEY COMPLETED R 09/24/2015
--	---	---	---

NAME OF PROVIDER OR SUPPLIER

STREET ADDRESS, CITY, STATE, ZIP CODE

COLONIAL LONG TERM CARE FACILITY

340 SNOWHILL DRIVE
MOUNT AIRY, NC 27030

(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETE DATE
(C 166)	Continued From page 2 Rule, by not maintaining the HVAC/ventilation, grilles and their associated dampers free of hazards. This could affect all residents, staff and visitors if in the event of a fire the dampers do not close completely to contain the fire within the room of origin. Followup Findings on September 24, 2015: a. The HVAC grilles, ventilation grilles, and their radiation dampers have an excessive accumulation of dust/lint. Locations of specific examples include but are not limited to: i. Return in corridor near Bedroom 5,	(C 166) C166 Ai	Return in corridor near Rm 5 filter has been replaced. Maintenance w/ll maintain filters and HVAC grilles and dampers monthly	
(C 185)	Fire Safety-Rehearsals on Each Shift SECTION .0300 - PHYSICAL PLANT 10A NCAC 13F .0309 PLAN FOR EVACUATION (b) There shall be rehearsals of the fire plan quarterly on each shift in accordance with the requirement of the local Fire Prevention Code Enforcement Official. (c) Records of rehearsals shall be maintained and copies furnished to the county department of social services annually. The records shall include the date and time of the rehearsals, the shift, staff members present, and a short description of what the rehearsal involved. (f) This Rule shall apply to new and existing facilities. This Rule is not met as evidenced by: 1. Based on Record review and interview with Manager the facility failed to rehearse the fire plan quarterly on each shift. This deficiency affects all residents, staff and visitors by not having trained staff and cooperative residents when a there is a need to evacuate the building.	(C 185)		

NAME OF PROVIDER OR SUPPLIER	STREET ADDRESS, CITY, STATE, ZIP CODE
------------------------------	---------------------------------------

340 SNOWHILL DRIVE
MOUNT AIRY, NC 27030

Division of Health Service Regulation

2022

If continuation sheet 4 of 8

STREET ADDRESS, CITY, STATE, ZIP CODE

340 SNOWHILL DRIVE
MOUNT AIRY, NC 27030

4140

If continuation sheet 5 of 8

Division of Health Service Regulation

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION	(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER: HAL086002	(X2) MULTIPLE CONSTRUCTION A. BUILDING: 01 B. WING: _____	(X3) DATE SURVEY COMPLETED R 09/24/2015
---	--	---	--

NAME OF PROVIDER OR SUPPLIER
COLONIAL LONG TERM CARE FACILITY

STREET ADDRESS, CITY, STATE, ZIP CODE
**340 SNOWHILL DRIVE
MOUNT AIRY, NC 27030**

(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETE DATE
(C 189)	Continued From page 5 cover the hole through the ceiling at the following locations to include but not limited to: iv. Mop Room 11. Based on observation, the Building was not maintained in a safe and operating condition, because the electrical power system was not being operated or maintained. This would affect all staff, by allowing unsafe conditions to persist. Followup Findings on September 24, 2015: a. There was a "telephone cable" running in the corridor door opening, interfering with the proper closing of the door to the Dining Room. 13. Based on Observation, the facility failed to provide necessary equipment to ensure clean potable water supply. Followup Findings on September 24, 2015: a. The shampoo sink in the Beauty Shop had a hose long enough to reach gray water which was not equipped with a vacuum breaker to prevent backsiphonage of gray water back into the potable water plumbing lines.	(C 189) C 189 11A C 189 13A	Mop Room. telephone cable will be RAN threw the wall And any openings covered with Fire chack shampoo sink hose will be shortened AS to not not touch the floor	2 wks 2wks 2wks